

## JANUARY 2025 | PROGRESS SUMMARY



### Stormonth Elementary School

#### Winter Break Progress

- A temporary partition was built around the gym bathrooms.
- Stairway three and the gym bathrooms were demolished.
- Door openings at the gym bathrooms were modified.
- Stairway three treads were leveled.



Temporary partition around the gym bathrooms.



Stairway three – before, during and after demolition and leveling (remains unfinished).

## Stormonth Elementary School

### Happening Now

- Stairway three's walls are being patched and painted.
- Completing underground plumbing rough-ins for the gym bathrooms.

### Looking Ahead

- Gym bathroom floors will be leveled and have concrete poured.
- Layout walls and progress on mechanical, electrical, plumbing and fire protection rough-ins in the gym bathrooms.
- Replace flooring and base in stairway three.
- Finish upgrades to front office security.
- Complete casework additions and modifications.



Walls are being patched and painted in stairway three.



Underground plumbing rough-ins for the gym bathrooms.



### Save the Date!

Stormonth is turning 90! Join us at Stormonth Elementary on Thursday, April 3, 2025, as we look back on 90 years and look forward to many more by celebrating its new facility renovations.